

Williams Visit Report

School: Bel Air Elementary

Visit Date: September 6, 2007

Facility Notes:

Paperwork shows that all problems noted in the Fall 2006 Facilities Report have been resolved.

1. Interior Surfaces:
 - a. Rm. 1 has slightly damaged tile ceiling
 - b. Rm. 21 has a wood baseboard outside that is cracked and worn but is in the process of being repaired.
2. Hazardous Materials:
 - a. In Rm. 5 there are asbestos tiles that need to be replaced.
3. Electrical:
 - a. Rm. 4 has 3 light banks out in the ceiling
 - b. Rm. 21 has a ceiling light out.
4. Drinking Fountain:
 - a. Rm. 27 has a water fountain with low water pressure.
5. Restrooms:
 - a. Rm. 13 the Girls RR is used for storage. The Boys RR is unisex.
6. Playground/School Grounds:
 - a. The playground by the Main Office, has a raised concrete cylinder on the side, in the landscape area.
 - a. On the lawn of the Playground Field there is one wet sinkhole and one wet mud patch.