

Williams Visit Report

School: El Monte Elementary

Visit Date: September 5, 2007

Facility Notes:

Work orders were submitted for work in progress or already completed prior to the team visiting the facilities.

1. Interior Surfaces:
 - a. Problems with ceiling/wall tiles were seen in the Library, where they are thicker than others and protruding
 - b. Electrical Room has a hole over the door on the interior side
2. Hazardous Materials:
 - a. Peeling paint outside the Boys and Girls RR by Rm. 22
3. Pest/vermin Infestation:
 - a. A bird's nest was seen in the eaves across from Rm. 22
4. Restroom:
 - a. Upper Grade Boys RR has a loose sink
 - b. Upper Grade Girls RR has chipped tiles in the last stall (handicapped stall) and 2 chipped tiles in the middle stall (work order MO14660 for middle stall)
 - c. Girls RR by Rm. 22 has a small hole in the ceiling and cracked tiles
5. Overall:
 - a. Cleanliness of the school is extremely good.