

Williams Visit Report

School: Hillview Jr. High

Visit Date: September 11, 2007

Facility Notes: Rough and uneven pavement that was noted during the Fall 2006 visitation has not yet been resolved. Most other problems have been fixed.

School Grounds: An area of high concern is the lower field on the school grounds. There is an open drain that is big enough to step into or even for a small child to fall into and cause serious injury. It is also covered by overgrown grass and not easily noticeable. Also, there are many gopher mounds/holes and the surface is very uneven.

Although the school does not use this field, there is nothing keeping the community out of this field after school hours or on the weekends.

The upper field has sprinkler heads sticking up about 1.5”.

Problems with the field areas were reported last year also.

Windows: window trim in the Cafeteria buckled and loose

Interior Surfaces: a few ceiling tiles loose/missing, in Rm. 208, 2 of the 3 sinks are not operational.

Structural Damage: Concrete has risen in many areas around the campus causing trip hazards

Electrical: In Rm. 407 there is network cabling bundled and hanging near the T.V.

Pests/vermin: ants in the Library

Drinking Fountains: low water pressure in drinking fountains (all are functional, though).

The overall condition of the school facility was rated as very good. The team commented that the school is very clean and well maintained.