

Williams Visit Report

School: Bayview Elementary

Visit Date: September 4, 2007

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. A-Bldg – Graffiti
 - b. Pre-school rm. M-4 – Graffiti on the door of this room
 - c. M-Wing – Graffiti on entry doorway to wing.
 - d. The Staff Lounge – paint peeling on the outside of a door.
 - e. Pre-school room M-4 – boarded up window.
2. Electrical
 - a. Lights were out in the hallway outside M-3
 - b. Lights were on in the Office, the office also has warped diffusers
3. Playground/School Grounds
 - a. A-Bldg - Graffiti on exterior walls
 - b. M-Wing – Graffiti on exterior brick wall
 - c. The pre-school playground and the playground in the back of the school are both under construction. The new pre-school playground will have a drinking fountain, which was lacking on the old yard.
4. Overall Cleanliness: This facility seems to have the most problems with graffiti. The custodian has ordered more paint so this issue may be resolved.