

Williams Visit Report

School: El Sobrante Elementary

Visit Date: August 21, 2007

Facility Notes:

1. Mech. Systems
 - a. Rm. 7 - Sink plugged
2. Windows/Doors/Gates/Fences (in & out)
 - a. EMERGENCY CONDITION: Front Doors have no spring and are propped open. Doors are extremely heavy and would cause severe damage to an individual if they were to get caught on them swinging closed.
3. Interior Surfaces
 - a. Chipped floor tiles throughout building
 - b. Rm. 17 cabinet next to entrance has peeling paint.
 - c. Hallway by Rm. 13 Ceiling tile missing
 - d. Rm. 13 – Missing ceiling tile by heater as stained ceiling tiles.
 - e. Rm. 8 missing paint
 - f. Cork ceiling tiles throughout hallways are deteriorating, **as stated in the 2005-2006 SACR and has yet to be addressed.**
4. Fire Safety
 - a. Rm. 7 – Fire extinguisher outdated
5. Electrical
 - a. Library – 2 missing diffusers
 - b. Rm. 15 – diffuser missing
6. Restrooms
 - a. Main Hallway (Boys) – Broken door handle; broken faucet, faucet does not turn off
 - b. Rm. 7 (Girls) – Broken door
 - c. Main Hallway (Girls) – Broken door, Missing faucet button
 - d. ADA RR – No Railing behind toilet
 - e. Identify RR by Rm. 15,16
 - f. One of the restrooms by Rm. 15/16 is being used as storage.
 - g. Cafeteria RR needs to be opened – doors are too narrow and not up to ADA standards.

Williams Visit Report

7. Playground/School Grounds
 - a. Concrete is cracked and uneven pavement, **this was reported in the 2005-2006 SARC and has yet to be addressed.**
 - b. Baseball backstop fence broken
 - c. Ramp to field is cracked.

8. Overall Cleanliness - FAIR