

Williams Visit Report

School: Fremont Elementary

Visit Date: 9/2/08

Facility Notes:

1. Mechanical Systems
 - a. Boiler in MPR is old and in need of replacement
2. Interior Surfaces:
 - a. Peeling paint on interior door surface of Boys' and Girls' restroom outside Room 5
 - b. Peeling paint on window frame in Room 17
 - c. Peeling paint on interior doors in Rooms 4-6, 12, K2
3. Structural Damage:
 - a. Dry rot on canopy supports at end of C & D wings (Noted last year)
4. Electrical:
 - a. Missing light diffuser and 1 light out in room 10
 - b. 2 lights out in rooms 15, 19, & 23
5. Drinking fountains/Sinks:
 - a. Loose waterspout at sink in room 9
6. Playground/School Grounds (Safety Issues):
 - a. Outside sidewalks are cracked and have trip hazards- marked in red
 - b. Playground asphalt is cracked and raised in some locations