

Williams Visit Report

School: El Monte Elementary

Visit Date: 9/11/08

Facility Notes:

1. Interior Surfaces:
 - a. Paint is peeling off cabinets in Room K-1
2. Electrical:
 - a. Electrical faceplate missing in Room 6
3. Drinking fountains/Sinks:
 - a. Sink not operational in Room 6
4. Restrooms:
 - a. Light covers in bathroom missing in Room K-1
 - b. One sink needs caulking in boy's bathroom near Room 15
5. Playground/School Grounds:
 - a. Good condition