

# Williams Visit Report

**School: Glenbrook Middle**

**Visit Date: 9/17/08**

## **Facility Notes:**

1. Interior Surfaces:
  - a. Music room has torn curtain
  - b. Unable to inspect restrooms for interior surface defects
  - c. 300 Wing—In Room 304 repair wire mold on ceiling; repair hanging curtain
  - d. In Room 307 repair hanging cabinet door
2. Safety Issues:
  - a. See Playground/School Grounds (g & h) below
3. Structural Damage:
  - a. 1 cafeteria table needs repair
4. Electrical:
  - a. Replace missing conduit hanger in main hallway of 400 Wing
  - b. Replace light diffuser in 600 Wing hallway
  - c. Repair schedule 80 conduit and reattach/hang/secure cable at same location in 800 Wing
  - d. 900 wing— Replace 3 electrical box covers in Room 903
  - e. Repair exit light/conduit above door in girl's locker room
  - f. Repair several overhead lights in Library
5. Drinking fountains/Sinks:
  - a. Repair minor dripping faucet in 300 Wing
  - b. Adjust faucet/bubbler in Room 901
6. Restrooms:
  - a. Restrooms have below standard low lighting
  - a. Restrooms unusable/converted to storage in 300 Wing
  - b. Repair soap dispenser in Boys' restroom in 400 Wing
  - c. Reattach soap dispenser and replace exterior room sign in Girls' restroom in 700 Wing
  - e. Repair and clean floor tile in Boys' restroom in 700 Wing

# Williams Visit Report

## Facility Issues continued (Glenbrook Middle)

7. Playground/School Grounds:
  - a. Repair concrete at front door area of 300 Wing
  - a. Address hazards of aging wooden benches outside of 300 Wing
  - b. Address trip wall hazard related to copper pipe protruding from ground
  - c. Repair stucco near exterior front door in 900 Wing
  - d. Patch small hole in stucco outside of Gym office door
  - e. Picnic Area: Wooden rails and related benches are worn, decayed and have splinters—need to address
  - f. Track: Area off corner of blacktop-B-ball courts has broken chunks of debris dumped in middle of track
  - g. One of nearest ball fields is dry, cracked and has several (4-6) deep (6-12") holes and ruts that are hazardous