

# Williams Visit Report

**School:** Lincoln Elementary

**Visit Date:** September 22, 2008

## **Facility Notes:**

1. Interior Surfaces:
  - a. Hallway in front of Rm. 106 – tile in Hallway is cracked causing a trip hazard.
2. Structural Damage:
  - a. Multi-Purpose Rm – Crack on exterior stucco wall needs to be repaired.
3. Electrical:
  - a. Library – Electrical diffusers are bending and curling upwards
  - b. Lights out in the Kitchen and Multi-Purpose Rm.
10. Restrooms:
  - a. 1<sup>st</sup> floor Girls Restroom – continuous running water from faucet.
  - b. 1<sup>st</sup> floor Boys Restroom – Clogged urinal and continuous running water.
  - c. 2<sup>nd</sup> Floor Boys Restroom – urinal out of order
  - d. 2<sup>nd</sup> Floor Girls Restroom – Disabled toilet out of order