

Williams Visit Report

School: Nystrom Elementary

Visit Date: September 9, 2010

Facility Notes:

1. Interior Surfaces
 - a. Multi-Purpose Room – Ceiling tile missing
 - b. Room 7 – Unattached wall mirror within student access
2. Electrical
 - a. Multi-Purpose Room – Electrical cover plates missing on stage floor
3. Restrooms
 - a. Boys Restroom by MPR – Urinal not draining properly
 - b. Girls Restroom 2nd floor – Toilet seat loose; open wire box
4. Fire Safety
 - a. Multi-Purpose Room – Fire extinguisher in MPR missing glass cover
5. Sinks/Fountains
 - a. Multi-Purpose Room – Drinking fountain in front of MPR missing spout
 - b. Outside Room 3 – Fountain across from room 3 not working
6. Overall Rating: GOOD