

# Williams Visit Report

**School:** Antioch Middle

**Visit Date:** September 26, 2007

## **Facility Notes:**

### **Interior/Exterior Surfaces:**

Gym—hole in 2<sup>nd</sup> beam, center

Rm. 204—crack in wall below bulletin board

MPR—stage curtains are ripped

600 Portables—carpets are stained and torn

The outside of 400 Hallway needs to be power washed

The carpet in add-on office needs replaced

### **Hazardous Materials:**

Lead paint peeling on exterior surfaces between 100-200 wings

### **Electrical:**

MPR—5 overhead lights are out

Rm. 102—2 light covers missing; 2 lights out

Rm. 104—2 light covers missing; 1 light out

Gym Hallway—Damaged light diffuser

Rooms 101, 103, 210—missing light covers; have burned out lights

Library—has light out

### **Drinking Fountains:**

Noted low pressure in drinking fountains in the 100 academic wing

### **Restrooms:**

100 wing girls' bathroom has sink faucet issues, and a leaking toilet

### **Playground/School Grounds:**

Tripping hazards from rutted and uneven surfaces in the field area

Exposed rebar on track curb