

Williams Visit Report

School: Prospects High

Visit Date: September 27, 2007

Facility Notes:

Interior Surfaces

In upstairs classrooms and offices the carpet is worn and in some places buckled
Atrium ceramic tile is cracked causing a trip hazard. Work order has been submitted
Classrooms throughout have some ceiling tiles that are stained, missing and some with holes

Safety Issues

A few cabinets are not earthquake proofed

Electrical

Rm. 201 has loose data connector

Restrooms

2nd floor women's restroom has a counter with peeling laminate
Upstairs men's restroom has graffiti carved into partitions

Grounds

Missing utility covers