

Williams Visit Report

School: Rodeo Hills Elementary

Visit Date: September 28, 2007

Facility Notes:

Mechanical systems:

The book room on the stage needs ventilation.

Windows, Doors, Gates, and Fences:

Door to outside by the 500 wing: The door closure is broken.

Main entrance to the Cafeteria: The door needs weather-stripping at the top.

Room 555: One window is not opening properly. It is tagged for repair.

Interior Surfaces:

Hallway by Room 564: There is a damaged ceiling tile by the exit sign.

There is one chipped floor tile and two cracked floor tiles.

Cafeteria: There is a chipped and missing tile by the Exit #208

Hazardous Materials:

The stucco needs to be painted in several places outside where the children have played ball against the walls.

Structural Damage:

There is a large hole in the stucco on the wall on the playground outside of the cafeteria.

K Play area: There is a chipped section in the concrete/stucco near one of the circular "windows". A wire (not electrical) is sticking out of the wall.

Electrical:

Library: There are three banks of lights out.

Restroom – Downstairs: One toilet is out of order.

Boys Restroom by the Cafeteria: One faucet does not shut off. One toilet seat is loose.

Girls Restroom by Rm. 558: 2 stalls out of order and locked.

Roofs

ALL of the downspouts are missing. (These had been stolen and new ones re-ordered.)