

# Williams Visit Report

**School:** Cambridge Elementary

**Visit Date:** September 13, 2007

## Facility Notes:

1. Interior Surfaces
  - a. Rm. 10 – Loose ceiling tiles
  - b. Rm. 1 & Rm. 8 – Tiles on floor chipped and buckling
2. Structural Damage
  - a. Latch on center of stage floor needs to close better
3. Fire Safety
  - a. Rm. 31 – Extinguisher needs to be mounted.
4. Electrical
  - a. Rm. 22 & R. 21 – Light covers missing.
  - b. Rm. 9 – Exposed cord to overhead.
5. Drinking fountains
  - a. K playground – Chipped wood around faucet
  - b. Rm. 6 – low pressure in faucet and in sink.
6. Restrooms
  - a. Soap dispenser needed in cafeteria on wall.
7. Playground/School Grounds
  - a. Very muddy play ground area – it is unusable. The city controls the sprinklers in this area and the school has a call into the city.
8. Overall Cleanliness: Good