

Williams Visit Report

School: Oak Grove Middle

Visit Date: September 11, 2007

Instructional Materials: Facilities Only Visit

Facility Notes: No Extreme Deficiencies noted. During the visit a hazardous bulletin board was removed and a soap dispenser was unblocked.

1. Windows/Doors/Gates/Fences (in & out)
 - a. E1 had a damaged window screen
2. Interior Surfaces
 - a. Chipped/broken laminated counter tops in C4 & C5
 - b. C wing needs interior paint
3. Fire Safety
 - a. No fire extinguisher in C5 though bracket is still on wall (if there is a "Fire Ext Inside" sign displayed, there should be a fire extinguisher)
 - b. D1 is congested with materials
4. Electrical
 - a. Light diffusers are an issue throughout the school
 - b. Lights weren't working in A2, Library and the restrooms in the Multi-use Room
 - c. Need light covers in A2, C4, D1, & Library
 - d. Missing light cover plate in G2
 - e. Missing data terminal cover plate in F7
 - f. Electrical wires need to be redistributed in C5, currently present a trip hazard
5. Drinking fountains
 - a. Loose faucet in C4
 - b. Low water pressure in D1
 - c. Address water needs for external use (hose for exterior garden is connected to sink in G2)
6. Restrooms
 - a. 2 loose sink faucets in D-wing Boys' RR
 - b. General cleaning is needed around urinals and toilets in D-wing Boys' RR
 - c. 1 dispenser missing towels in Multi-use Girls' RR

Williams Visit Report

(Oak Grove Middle continued)

7. Roofs
 - a. A-wing—roof run-off

8. Playground/School Grounds
 - a. Front of C1—all thread brackets are loose
 - b. B-Wing—outside, there is a leaking valve in the grass area