

Williams Visit Report

School: Shore Acres Elementary

Visit Date: September 18, 2007

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. Caulking is chipped, broken and missing in Rooms: 28, 8
 - b. Rm. 1 – The rear door needs a weather strip.
 - c. Rm. 28 – Upper window frames are rotted.
 - d. Rm. 28 – Cracked window.
 - e. Plastic windows in Rooms: 11, 13, 14
2. Hazardous Materials
 - a. Rm. 1 – Chipped paint on ledge above sink.
3. Structural Damage
 - a. 400 Wing, Outside Boys RR – Bottom of wall is crumbling and paint is hanging.
 - b. Outside Rm. 4 – There is a hole in the bottom of the wall near other patches.
4. Fire Safety
 - a. Rm. 28 – Books stacked on top of heater.
5. Electrical
 - a. Rm. 8 – One light burned out.
6. Drinking fountains
 - a. Rm. 28 – low pressure
 - b. Library Office – low pressure
7. Restrooms
 - a. 300, Girls RR – Toilet seats need tightening, cracked and broken toilet seat cover dispensers.
 - b. 400, Boys RR – Toilet seats need tightening.
8. Playground/School Grounds
 - a. Crumbling concrete in walkway outside office also on adjacent corridor.
 - b. Large crack in concrete outside of Girls RR 300

Williams Visit Report

(Shore Acres continued)

- c. Repair work outside of Rm. 1 has disintegrated.
- d. Playground: Part of grassy area floods.

9. Overall Cleanliness: GOOD

Review of Previous Years' Reported Situations:

All items on the list from Dr. Ovick's letter are reported or observed to have been rectified with the following exceptions:

1. The section of the grass that floods and is uneven due to the sprinkler system is still a problem.
2. The windows in rooms 11, 13, and 14 are reported to still have some plastic windows.
3. The issue regarding windows that have missing or broken caulk is still a problem. Some windows appear to be in a condition that makes it possible to easily push them out of the frame, since the caulking is missing or severely weakened.