

# Williams Visit Report

**School:** Harding Elementary

**Visit Date:** September 19, 2007

## Facility Notes:

1. Mech. Systems
  - a. Inside the Boys' RR in the Cafeteria—main water pipes, and control valves for the fire suppression sprinklers are exposed; not caged and secured.
2. Interior Surfaces
  - a. Computer lab— access doors in the floor for computer hook-ups were off their hinges exposing connectors, receptacles and wires.
3. Fire Safety
  - a. Auditorium—two fire extinguishers that were not inspected and certified during the last cycle.
  - b. Media Center—no fire extinguisher
4. Drinking fountains
  - a. A Wing & Cafeteria—very low water pressure
5. Playground/School Grounds
  - a. Front of building (on Fairmount Avenue), western edge—main gas pipes not caged and secured
  - b. Corner of building (Fairmount & Ashbury Avenues)—large water pipes, valves and electrical pumps not caged and secured
6. Overall Cleanliness: The school is extremely well kept.

None of the same items from the Fall 2006 Facilities Notes report were noted.