

Williams Visit Report

School: De Anza High

Visit Date: September 11, 2007

Facility Notes:

1. Mechanical Systems
 - a. HVAC cover plate was missing in Room 256
2. Windows/Doors/Gates/Fences (in & out)
 - a. There were also broken windows observed in Rooms 109, 202, 203, 205, 251, 252, 255, 303, 306, 353, 354, 355, Library, **many of the same broken windows were mentioned in the 2005-2006 SARC and have yet to be addressed.**
 - b. Rooms 258 & 259 had damaged cabinet doors
3. Interior Surfaces
 - a. Boys Locker Room
 1. There are a number of broken lockers
 2. Repair hole in the plaster.
 - b. There are damaged floor tiles in Rooms 5, 110, 204, 257, 258, Cafeteria
 - c. There are missing/damaged ceiling tiles in Rooms 2, 3, 7, **many of the same ceiling tiles were mentioned in the 2005-2006 SARC and have yet to be addressed.**
 - d. There is peeling paint in Rooms 356 & 357
 - e. The Cafeteria's walk-in freezer box has visible rust spots
4. Electrical
 - a. **The 2005-2006 SARC stated the following: The lights, diffuses and covers need to be repaired. We did not see evidence of repairs.**
 - b. Problems with electrical lights/missing diffusers were seen in a number of rooms (5, 108, 109, 110, 201, 202, 203, 204, 251, 252, 253, 255, 256, 257, 258, 259, 302, 306, 308, 353, 354, 356, 357, 451, Cafeteria and hallways)
 - c. The Boiler Room had its electrical panel off and was full of debris
5. Drinking fountains
 - a. Outside Room 354 - leaking spigot
6. Restrooms
 - a. Main Boys' RR - urinal is missing
 - b. Main Girls' RR-

Williams Visit Report

1. There is a leaking toilet
 2. One is plugged and not working.
 - c. There was quite a bit of graffiti in the RR's by the Cafeteria.
 - d. Restrooms need to be kept cleaner.
7. Playground/School Grounds
- a. **2005-2006 SARC stated the following: The asphalt on the playground needs to be repaired.** Please see our findings.
 - b. Outside grounds had cracks, uneven surfaces and were not clean overall.