

Williams Visit Report

School: Helms Middle School

Visit Date: September 14, 2007

Facility Notes:

1. Windows, Doors, Gates - Broken windows were pervasive campus-wide, **this was reported in the 2005-2006 SARC and had yet to be addressed.**
2. Interior Surfaces
 - a. Chipping paint, cracked stucco, and stained ceiling tiles were pervasive campus-wide.
 - b. Carpet in Internet room is a trip hazard.
3. Fire Safety
 - a. Room 214 – no extinguisher
 - b. Smoke detector cover missing in 100 hall
4. Electrical
 - a. Room 211 – Network wire mold hanging off wall
 - b. Lights not working and diffusers missing in many rooms
 - c. Room 241 – electrical box for clock uncovered
 - d. Cafeteria – lamp ring loose
5. Drinking Fountains – Low pressure found in many fountains; all fountains need to be checked, **this was mentioned in the 2005-2006 SARC and has yet to be addressed.**
6. Restrooms
 - a. Most RR without paper towels
 - b. Girls upstairs RR – Mirror frame needs to be removed.
 - c. Boys upstairs RR – Missing urinal and loose faucet.
7. Sewer - Down spouts missing or broken throughout school site.
8. Playground/School Grounds
 - a. No problems observed but not in great shape. Much of the grounds are being used for new school construction.
9. Overall Cleanliness: Fair

Williams Visit Report