

Williams Visit Report

School: Antioch High School

Visit Date: 9/22/08

Facility Notes:

1. Mechanical Systems
 - a. Thermostat cover is missing in Room 610
 - b. Boys' restroom in 200 Wing —vent fan not operational
2. Interior Surfaces:
 - a. Wood doors need painting in Room 401
 - b. Wood doors need painting or replacing in 500 Wing, 700 Wing, and 900 Wing
 - c. Small area of peeling paint about stall #1 in Girls' restroom in 700 Wing
 - d. Torn wallboard in Room P15
 - e. Exposed bolts in wall of lobby to small Gym
3. Safety Issues:
 - a. Lack of intercom system at Admin Asst. area may contribute to safety issue: APs cannot hear bells, emergency notices, other audio communications
4. Electrical:
 - a. Wire management of TVs, projectors, computers needs to be addressed—Wires hanging, extension cords without surge protection being used in Rooms 602, 605, and 608
 - b. Light out in Room 1118
10. Drinking fountains/Sinks:
 - a. Very low pressure in drinking fountains in Main Gym (noted last year) and Lobby
 - b. Faucet handle missing in Boys' locker room sink #1
11. Restrooms:
 - a. Portable restrooms closed for repair due to vandalism
 - b. Faucet handle missing in room 401

Williams Visit Report

School: Antioch High School

Visit Date: 9/22/08

Facility Notes:

12. Playground/School Grounds:
 - a. Asphalt areas on playgrounds, in sports areas and parking lots need repair (noted last year)
 - b. Pool deck needs to be repaired or replaced
 - c. Pool shell needs to be replaced
 - d. Crack in concrete running entire length of 900 Wing