

Williams Visit Report

School: Harding Elementary

Visit Date: September 9, 2008

Facility Notes:

1. Interior Surfaces:

- a. Stained ceiling tiles near media center need to be replaced
- b. Stained ceiling tiles in room 147 need to be replaced
- c. Stained tiles in hallway in front of Media Center

2. Electrical:

- a. Electrical outlet outside café not covered
- b. No light diffusers on 2 lights in front of rooms 205, 207
- c. Computer Lab access doors in floor for computer hook-ups
Were off their hinges exposing wires/connectors, etc.- still not resolved from last year

3. Restrooms:

- a. Hand dryer not working in Boys' restroom near room 147

4. Playground/School Grounds:

- a. Outside gas valve at side of building near auditorium needs to be caged
- b. Water valve at front of building is secured by chain but is not caged
- c. Boys' restroom in café has valve and pipe secured but not caged

5. Overall Cleanliness – EXEMPLIARY