

Williams Visit Report

School: Tara Hills Elementary

Visit Date: September 26, 2008

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)

- a. **Extreme Deficiency:** Doors on both sides of N wing – posts need to be replaced or removed. If removed, another method to stop the doors must be used. The door without a stopper is falling off hinge and scrapes against the asphalt. This is a main door and should be addressed soon.
- b. Outside door near the café needs to be painted
- c. Dry rot on outside beams of Cafeteria and on bathroom floors
- d. Paint peeling on front door and on door of Rm. 13

2. Safety Issues:

- a. Book case not secured to wall in Rm. 13
- b. In parking lot fire hydrant is exposed on one side – needs protective barrier.

3. Structural Damage:

- a. Pipe needs to be fixed on both sides of Bldg. N

4. Electrical:

- a. Faceplate missing on outlet in hallway by kindergarten
- b. Lights out in hallway P-7 and Rm. N3

10. Drinking fountains/Sinks:

- a. Sink faucet in room N is very loose and needs to be secured, it is putting stress on pipe

11. Restrooms:

- a. Need vent filters in Girls' bathroom

12. Playground/School Grounds:

- a. The perimeter fence has holes and is falling down and needs to be secured. The higher fence installed on most of the grounds should be extended through the last part of the parking lot near Wing N.
- b. Fence around community garden has hole near a steep ravine area

Williams Visit Report

- c. Need protection around fire hydrant in back lot near N building
Fire hydrant needs additional poles, new side fence, back fence and front pole is bent.
- d. Graffiti on the Kindergarten and Main Playgrounds and water fountains.
- e. Back BN Fence not attached on top or bottom.

13. Overall Cleanliness - GOOD