

Williams Visit Report

School: Pittsburg High School

Visit Date: September 20, 2007

This was a Facilities Only visit.

Facility Notes: Of the 31 issues noted in the Fall 2006 visit 25 have been resolved, 2 didn't have access to lights fixture and cannot be replaced and 1 is a locked/unused room. No reason was given for the other 3 problems.

The East Campus (300 buildings) will be demolished in June 2008 to make way for a new high school.

Interior Surfaces: Missing ceiling tile was noticed in the Boy's Gym room, Rms. 240, 325 and 329.

Missing/broke wall tiles were in the hallway adjacent to Rm. 207 and 218

Two sinks don't drain or drain slow in Rm. 133 – Home Economics.

Paneling in the foyer of the Big Theater needs replacing.

Rm. 127 has missing cover base in the hallway at various locations.

Restrooms: Problems with restroom's were seen in the Boy's Gym that has a leaking toilet; the Boy's RR by the Cafeteria has no paper towels, one stall with no TP or holder and a broken drinking fountain outside of RR; the Boy's RR next to Rm. 219 is closed – 1 inoperable urinal; the Girl's RR by Rm. 231 has 2 stalls locked; the Girl's RR by Rm. 235 has a faucet missing, two locked stalls and graffiti; the Boy's and Girl's RR adjacent to Rm. 319 are locked; the Boy's RR near Rm. 325 is locked and the Girl's RR by Rm. 330 is locked. Rm. 270 has missing baseboard and chipped ceiling paint in the RR.

Electrical: Lights were out/missing in the west side of the Girl's Locker, the Audio Visual hallway, the main Cafeteria (8 ceiling lights out) and Rm. 206 (no access to these fixtures). Rm. 310 has a data wire loose and strung through classroom.

Windows/Doors: The Boy's Locker has a broken exterior window.
A door is broken and blocked in the hall next to D Boiler Room.

Drinking Fountain: The drinking fountain outside Rm. 137 isn't working.

The overall condition of the school facility was rated as fair.