

Williams Visit Report

School: Foothill Elementary

Visit Date: 9/30/08

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. Need to replace 20 ft. section of south fence
2. Interior Surfaces:
 - a. Exterior paint chipping outside room K1 and A1
 - b. Ceiling tiles missing due to leak from pump in ceiling in Library
3. Safety Issues:
 - a. Sprung fire extinguisher holder in Room G1
4. Electrical:
 - a. Wire management issue in Rooms B5 and G1— too many power cords connected to single extension, hanging from equipment loosely.
5. Drinking fountains:
 - a. Faucet handle missing on interior drinking fountain in room K1
6. Restrooms:
 - a. Boys' restroom in B pod is missing a urinal-pipe and hanging attachments exposed (Unit on site, work order has been generated)
 - a. Same restroom needs floor and wall wash down—strong odor
 - b. No water pressure in Boys' restroom sink #2 in room A1
7. Roof:
 - a. Rusted through downspouts and gutters outside cafeteria
8. Playground/School Grounds:
 - a. Many outside surfaces in need of painting
9. Overall Cleanliness:
 - a. Campus is clean and orderly