

Williams Visit Report

School: Highlands Elementary

Visit Date: 9/29/08

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. Replace planks in ramp to room 35

2. Interior Surfaces:
 - a. Taped carpet seams in Music room
 - b. Ceiling strip falling in room 17 & 21
 - c. Missing carpet edging in room 21
 - d. Door needs painting in room 22
 - e. Torn carpet seams in room 2-B

3. Electrical:
 - a. Refrigerator plugged into power strip in room 12, 13, & 24

10. Drinking fountains/Sinks:
 - a. Drinking fountain outside library not working
 - b. Low pressure drinking fountain in room 12, 17, & 24
 - c. 1st-2nd playground fountain has low pressure
 - d. Low Pressure drinking fountain outside 5th hallway-drip-leak
 - e. Wash basin has no water pressure in room 5
 - f. Dripping faucet in room 11
 - g. No water in drinking fountain in room 35
 - h. Clogged fountains and lack of water pressure on Playground

11. Restrooms:
 - a. Boys' restroom by room 6 is missing tile
 - b. No pressure in Boys' restroom sink in 1st, 2nd grade hall
 - c. Girls' restroom 5th hallway has clogged left sink
 - d. Leaking pipes in 3rd Hallway Girls' restroom
 - e. No water in 3rd Hallway Girls' restroom
 - f. Missing floor tile in room 5