

Williams Visit Report

School: Hillview Junior High

Visit Date: 9/29/08

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. Ceiling tile needs repair in Portable 6
 - b. Entry door knob assembly needs to be tightened in Girls' restroom in Bldg. 100
2. Interior Surfaces:
 - a. Cabinets in Portable 6 need to be secured
 - b. Baseboard needs to be repaired/replaced in room 116
 - c. Cabinets need to be secured in Room 116
 - d. Thermostat needs repair in Room 207
3. Electrical
 - a. Issue with light diffuser in Girls' locker room
 - b. 1 light out in Room 103
 - c. Wall plate in front of Room 405 needs to be tightened
4. Drinking fountains/Sinks:
 - a. Loose faucets on drinking fountains in Boys' locker room, quad area, gym, girls locker room, and main building
 - b. Drinking fountain not working in Portable G
3. Restrooms:
 - a. Boys' restroom in 200 Wing has low water pressure in toilets, loose toilet seats
 - b. Girls' restroom toilets in 200 Wing have low pressure flush
 - c. Sink in Boys' restroom in Bldg. 100 needs to be re-secured/tightened
4. Playground/School Grounds:
 - a. Irrigation issue in field
 - b. Lawn area, track area & black top issues with trip and fall hazards, holes, etc. have been painted orange but not repaired (continuing problem)
 - c. Exterior trim of Main Bldg. needs to be inspected for seal, priming, and painting needs

Williams Visit Report

Facility Notes continued (Hillview Junior High):

5. Roofs:
 - a. Flashing/gutter needs require review
6. Overall Cleanliness:
 - a. Excellent