

# Williams Visit Report

**School:** Antioch High

**Visit Date:** September 25, 2007

## Facility Notes:

### Mechanical Systems:

Shop Room: No heat

Room 1117: Teacher and students indicated that the room is cold all the time.

### Windows/Doors/Gates/Fences:

Library: Edge of door has chipped wood and paint.

Room 303: There is a cracked window.

Gym: The base vents on the storage double doors need to be replaced. They are bent/broken.

Foyer by Theater: There is a broken lock on one of the front doors. It is currently chained closed.

200 Wing: There is a door transition that needs attention. Parents complain that its a slipping hazard.

Room 501: The skylight window is cracked.

### Interior Surfaces (floors, ceilings, walls and window casings)

Library: Trip hazard on floor near library office reported by librarian. The tape, which covers the wiring, comes loose. Perhaps a more permanent solution could be constructed.

Room 606: Some ceiling tiles are missing.

Portables 2, 7, 9: The tackboard is damaged.

Portables 6,7,8: The carpet needs replacement.

Portable #7: There are damaged ceiling tiles.

300 Wing Hallway: There are many stains in the ceiling.

500 Wing Hallway: Several ceiling tiles on the west side have been vandalized

Room 903: Some ceiling tiles are stained.

Room 910: Some ceiling tiles are stained.

600-700 Boys Restroom: There are some minor holes in the wall in the far stall.

Large Gym Women's Restroom: There is a hole in the wall caused by the doorknob.

Girls Restroom by Portables: The linoleum has become detached from the wall.

Computer Lab Door: Trim has cracked/broken.

### Structural Damage

Room 906: There is a major crack in the floor concrete which runs the length of the room.

Room 908: There is a crack in the concrete floor.

### Fire Safety:

There is a thick layer (approximately 6" deep) of pine needles by the tennis courts.

### Electrical:

Boys Restroom by Portables: Missing one diffuser.

Room 306: One bank of lights is out (tagged for repair)

# Williams Visit Report

Room 303: One group of lights is out (tagged for repair).  
Room 904: Two banks of lights are out (tagged for repair).  
Room 905: Three banks of lights are out and tagged for replacement.  
Room 906: Two banks of lights are out and tagged for replacement.  
Room 908: Two banks of lights are out.  
Room 403: One bank of lights is out and tagged for replacement.  
Room 901: Four banks of lights are out and tagged for replacement.  
Room 1118: One diffuser is missing  
Room: 1102: One light is out.  
Room 1117: One diffuser is missing.  
Room 902: Three light fixtures have burned out lights.  
Room 903: Two light fixtures have burned out lights.  
Room 910: One light fixture is out.  
Girls Restroom by Portables: Missing one diffuser. Missing one electrical cover plate.  
Shop: One ballast is out and has been ordered.  
Band Room: One ballast needs attention. No lights in that one. Broken and missing diffusers  
Main Gym: Two lights are out.  
Career Center: There are lights burned out.  
Air Conditioning Units (Back of portables??) There are holes in the screens that surround the units, large enough to create a danger to anyone who pokes a finger through the hole.

## **Drinking Fountains:**

In Room 610: Not working  
Outside Cafeteria: One valve (faucet) not working; low pressure on the other one  
Outside Men's Room by Cafeteria: Low pressure.  
Main Gym: Two drinking fountains have low pressure.

## **Restrooms:**

Girls Restroom 1100 Wing:  
•One leaky flushometer  
•One toilet seat loose  
•Paper towel dispenser broken

Girls Restroom 300 Wing -leaky valves in stall #1

Women's Restroom Outside Cafeteria:

- One loose toilet seat
- One sink faucet – low pressure

Girls Restroom by Portables: Water runs quite a while on one faucet before automatic shut-off. There was a large puddle on the floor (perhaps related).

Women's Restroom by the Gym-Three loose toilet seats

## **Playground/School Grounds**

1100 Wing West Entrance: Concrete walkway is cracked.

Walkways: Many are lifted by trees and pose a trip hazard.

600 Wing: There is a hole in the side walkway that needs a cover (valve area??).

700 Wing: There are sand bags at the bottom of the stairs toward the portables. Drainage problem exists during stormy weather.

Fields: Some trip hazards in transition areas by the softball field

## Williams Visit Report

Football bleachers: Some of the wooden floorboards need replacement.

Parking in the gym area: The handicap sign is down and a small post is sticking up.

G St. and 18<sup>th</sup> St. Perimeters: There are some sidewalk trip hazards and some low spots where signs have been removed.