

# Williams Visit Report

**School:** King Elementary

**Visit Date:** September 12, 2007

## Facility Notes:

1. Interior Surfaces
  - a. Floor tiles cracked & sinking - Rm. 10, Cafeteria
  - b. Computer Rm.
    1. Loose carpet, could be a tripping hazard
  - c. Lunch Room
    1. Water stains on ceiling tiles
  - d. Rms. 51/52
    1. Hole in Rug
  - e. Outside 5<sup>th</sup> grade Study Ctr.
    1. Water damage in ceiling
2. Hazardous Materials
  - a. 3<sup>rd</sup> gr. Study Ctr.
    1. Paint peeling in boys RR
3. Structural Damage
  - a. Lunch Room
    1. Cracked and sinking floor tiles
  - b. Outside in 2<sup>nd</sup> floor walkway
    1. Hole
    2. Sloping floor – tiles bending
  - c. Hallway outside Rm. 10
    1. Cracked and sinking floor tiles.
4. Electrical
  - a. Rm. 1
    1. Broken converter plate
  - b. Library
    1. Blinking light
    2. Broken ballast
  - c. Missing light covers - throughout outside of school
  - d. Rm. 31
    1. Light out
  - e. 3<sup>rd</sup> gr. Study Ctr.
    1. Light out
  - f. Rms. 51/52
    1. Light out

# Williams Visit Report

## (King Elementary continued)

- g. Rm. 42
  - 1. 2 light out (1 in front, 1 in back)
- h. Rm. 43/44
  - 1. Light out

### 5. Restrooms

- a. 3<sup>rd</sup> grade Study Ctr.
  - 1. Really bad smell & condition (boys & girls)
  - 2. No hand soap (boys & girls)
  - 3. Running urinal (boys)
  - 4. Loose faucet handles in sink (girls)
- b. Rm. 1
  - 1. No paper towels
- c. Lunch Room (girls)
  - 1. No TP
- d. Rms. 51/52
  - 1. Loose faucet
  - 2. No soap
  - 3. No towels

### 6. Playground/School Grounds

- a. By the flagpole - Graffiti on side of school and on roof