

# Williams Visit Report

**School:** Lincoln Elementary

**Visit Date:** September 18, 2007

## Facility Notes:

1. Windows, Doors, Gates
  - a. Rm. 107 – 2 broken windows
  - b. BB hole in window outside the elevator area
  - c. Broken glass 6<sup>th</sup> street entrance.
2. Interior Surfaces
  - a. Library outer wall chipped.
3. Electrical – Electrical box uncovered near main entrance
4. Drinking Fountains – Low pressure near MPR and room 112, **this was mentioned in the 2005-2006 SARC and has yet to be addressed.**
5. Restrooms
  - a. Girl's RR MPR stall doorstep broken
  - b. Overall appearance of Restrooms is very clean
6. Overall Cleanliness – Exemplary