

Williams Visit Report

School: Tara Hills Elementary

Visit Date: September 13, 2007

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. A large sheet of wood covers window at entrance.
 - b. North wing – doorstop needs to be repaired.
2. Interior Surfaces
 - a. Cabinets under stage don't close
3. Electrical
 - a. Cafeteria – Outlet by south wall is broken.
4. Pest/vermin Infestation
 - a. Ants in Cafeteria by refrigerator.
5. Restrooms
 - a. I-Wing
 1. Girls – seat cover dispensers are empty in one stall and graffiti in handicapped stall.
 2. Boys – one urinal doesn't flush and one urinal over flushes.
 - b. No paper towels by sink in N3 and N4.
6. Playground/School Grounds
 - a. There is graffiti on the cement bleachers.
 - b. Fencing around schoolyard temporary due to remodeling.
 - c. Graffiti on exterior door of I-Wing.