

Williams Visit Report

School: Verde Elementary

Visit Date: September 10, 2007

Facility Notes:

1. Windows/Doors/Gates/Fences (in & out)
 - a. Fence by backstop missing.
 - b. Some fence on Westside of the campus is missing.
2. Interior Surfaces
 - a. Kitchen – Leak in refrigerator forming puddle on floor.
 - b. A-02 – Clock doesn't work.
 - c. D-18 – Clock doesn't work.
3. Electrical
 - a. Main Office Hallway – Exit sign burnt out, lights need to be replaced.
 - b. A-01 – Light out, needs to be replaced, **this was mentioned in last year's visit and has yet to be repaired.**
 - c. C-27 – Clock missing
 - d. A-02 – Clock doesn't work
 - e. D-18 – Clock doesn't work
4. Drinking fountains
 - a. **The 2005-2006 SARC states “The drinking fountains need to be repaired” be see the following:**
 - b. Main Office Hallway – fountain has no water
 - c. Multi-Purpose Room – Not functioning
 - d. All outside drinking fountains do not have drainpipes.
 - e. B-Wing – water fountain has low pressure due to jammed pipe.
 - f. C-12 – Broken water fountain
5. Restrooms
 - a. Boys RR
 1. Graffiti
 2. Repair bad plaster
 - b. Girls RR off Multi-Purpose Room – Very foul odor.
 - c. Boys RR B-25
 1. Broken faucet
 2. Remove broken paper dispenser
 - d. Boys RR C-30
 1. No soap dispenser
 2. Graffiti
 3. Broken urinal
 4. No paper towels

Williams Visit Report

5. Broken paper towel dispenser
 6. Cracked window
 - e. Boys & Girls RR Main Office - missing caps on faucets
 - f. Girls RR C-Wing – Missing plaster
-
6. Playground/School Grounds
 - a. Graffiti on play structure. **This was reported in last year's visit.**
-
7. Overall Cleanliness: GOOD