

Williams Visit Report

School: Delta View Elementary

Visit Date: 9/9/08

Facility Notes:

1. Interior Surfaces:
 - a. Interior paint peeling at front of library entrance
 - b. 1 light out and old stain on ceiling tile in Room 158
 - c. Old leak one ceiling tile in Room 125

2. Structural Damage:
 - a. Cracks: left side wall at left front entrance hallway; upper portion of front atrium by left stairway; above stage in Multi-Use Room (left & right); cracks above girls' restroom door; and horizontal crack on wall adjacent to boy's restroom

3. Restrooms:
 - a. Cover for toilet paper dispenser missing in 1st Floor girls' restroom
 - a. 1 slow urinal, 1 urinal doesn't flush in 1st Floor boy's bathroom
 - b. Failed cartridge in last sink in 2nd Floor girls' bathroom
 - c. 2nd Floor- Clock receptacle needs cover