

Williams Visit Report

School: Fair Oaks Elementary

Visit Date: 9/15/08

Facility Notes:

1. Interior Surfaces:
 - a. In cafeteria there was a workman's table with a rusty vice attached to the end. The vice could be opened—asked janitor to secure it or remove the bench
2. Restrooms:
 - a. Boy's restroom next to Room 13—non-flush urinal did not have running water
3. Playground/School Grounds:
 - a. Picnic table in back yard is splintering—should be removed or painted to get rid of rough edges
4. Overall Cleanliness
 - a. Very well maintained—great condition for a 40-year old school