

Williams Visit Report

School: Rio Vista Elementary

Visit Date: September 24, 2008

Facility Notes:

1. Mechanical Systems
 - a. Multi Kitchen – Heater grid needs to be repaired
2. Interior Surfaces:
 - a. Room A1 - Remove or cover Pencil Sharpener
3. Hazardous Materials:
 - a. C5 – Put cleaners behind locked cabinet. Windex and 409 are accessible to students.
4. Electrical:
 - a. Lights out in the following areas:
 1. A1 – 3 lights
 2. B6 – 3 lights (single florescent bulb in each)
 3. Library – 2 lights
 4. Computer Lab – 2 banks out
 - b. Kitchen – Light fixtures are coming off on the end
5. Restrooms:
 - a. B-wing, Boys RR – Left sink faucet does not work.
 - b. C-wing, Girls RR – Knob broken off sink
6. Playground/School Grounds:
 - a. Grounds outside A2 – Need fill dirt for trenching work.
 - a. West outside sitting area – Gang graffiti and two broken benches
 - b. Play structure/Playground – Slide is boarded up and there is graffiti
 - c. Main Playground – Broken bench, sharp metal is exposed
 - d. Baseball field – Broken middle bench, center board needs to be replaced or bolted down
 - e. Baseball field – Backstop cyclone fencing needs to be repaired.
 - f. Playground – cracked bench in back area
7. Overall Cleanliness - GOOD