

Williams Visit Report

School: Bayview Elementary

Visit Date: September 4, 2008

Facility Notes:

- 1. Windows/Doors/Gates/Fences (in & out)**
 - a. Throughout - Exterior doors laminate and/or paint is peeling
 - b. Cyclone fence near YMCA has a hole
 - c. Bldg A - Push bar on right side of exterior door is missing
- 2. Interior Surfaces:**
 - a. Water stained ceiling tiles in Computer Lab.
- 3. Structural Damage:**
 - a. Sheetrock behind the urinals in D Bldg. Boys' bathroom has water stains/leaking
- 4. Electrical:**
 - a. Light diffusers are warped in many classroom, office
 - b. Restrooms: Front lights are out in most restrooms. When questioned custodian mentioned no electrical connection.
 - c. 5 lights out in Multi-Purpose Room
- 5. Drinking fountains:**
 - a. Lower grade playground – Water fountain on right has very low water pressure, cannot drink out of faucet.
 - b. Near Bldg C – Water fountain has very low water pressure, cannot drink out of faucet.
- 6. Restrooms:**
 - a. No toilet seat covers
 - a. Lower grade Playground Boys RR – Dispenser does not have appropriate paper towels.
 - b. C Bldg Boys RR – 1 Urinal does not flush.
 - c. D Bldg Boys RR – Urinal leaking, causing stains.
- 7. Playground/School Grounds:**
 - a. Graffiti on playground structure (lower grade playground)
- 8. Overall Cleanliness - GOOD**