

# Williams Visit Report

**School: King Elementary**

**Visit Date: September 19, 2008**

## **Facility Notes:**

1. Windows/Doors/Gates/Fences (in & out)
  - a. Graffiti on Windows: Library
  
2. Interior Surfaces:
  - a. Carpet is torn on the stairs by the library and Rm. 5
  - b. Ceiling tiles in need of replacement: Rm. 5, 12.
  - c. Flooring in Rm. 12 needs to be repairs, missing and cracked tiles.
  - d. Wall in Rm. 12 needs to be painted
  - e. Wall in Cafeteria near back entrances needs new metal sheeting.
  - f. Cafeteria curtains are torn and soiled.
  
3. Electrical:
  - a. Lights out
    1. Kindergarten classroom, Rm. 1, and Boys RR 32
  
4. Drinking fountains:
  - a. Kindergarten playgrounds – Drinking fountains turned off.
  
5. Restrooms:
  - a. Kindergarten – Paper towel dispensers empty
  - b. Girls by cafeteria –
    1. No soap
    2. No soap dispensers
    3. No toilet paper
    4. Last stall needs toilet paper dispenser
  - c. Boys RR by Rm. 32 –
    1. Bad Smell
  - d. Girls RR by Rm. 32
    1. Stall #1 – leak
    2. No paper towels
    3. No toilet paper
  
6. Playground/School Grounds:
  - a. **Extreme deficiency** - Play area – The steps leading up the play structure have exposed metal. The rubber covering on the steps has

## Williams Visit Report

been worn off making the steps both slippery and sharp. These steps pose a hazard to the students climbing the structure.

### 7. Overall Cleanliness – GOOD

**Facility Notes:**

School was rated with the overall cleanliness as **GOOD** with the exception of the graffiti scattered throughout the facility.