

Williams Visit Report

School: Montalvin Elementary

Visit Date: September 11, 2008

Facility Notes:

1. Electrical:
 - a. Rm. 129 – Plugs exposed near ceiling, need cover.
 - b. Rm. 127 – Flickering lights.
2. Drinking fountains:
 - a. Fountain near Rm. 100 leaking.
3. Overall Cleanliness – Exemplary – This facility was very clean and kept in excellent condition.