

# Williams Visit Report

**School: Mission Elementary**

**Visit Date: September 1, 2010**

## **Facility Notes:**

1. Overall Cleanliness
  - a. Throughout School Classrooms – Wheeled closed carts stacked with materials and items
2. Playground/School Grounds
  - a. Kindergarten Playground – Fencing has exposed links poking over fence edge in multiple areas
  - b. D Hallway – Missing board under D12 walkway
3. Windows/Doors/Gates/Fences
  - a. Room K1 – Broken glass in window
  - b. C Hallway – Missing railing/ramp outside of C5 due to vandalism, parts are on order; some fencing with exposed links at the top
4. Overall Rating: GOOD
  - a. Work orders submitted for above noted items.