

I. Williams Visit

School: Cambridge Elementary

Visit Date: September 14, 2010

Facility Notes:

1. Restrooms
 - a. Girls Restroom near Room 7 – Pipe corrosion under sink
2. Sinks/Fountains
 - a. Multi-Use Room – Sink in the back of room coming off the wall
3. Playground/School Grounds
 - a. Walkways –
 1. Holes in the cement outside of girls restroom near Rm. 17, tripping hazard;
 2. Outside Multi-Use room tripping hazard
4. Overall Rating: GOOD
 - a. Note: Work orders submitted for above noted items