

Williams Visit Report

School: El Monte Elementary

Visit Date: September 21, 2010

Facility Notes:

1. Electrical
 - a. Room 13, 23 – Two light panels out
2. Restrooms
 - a. Girls Restroom –
 1. Rusted pipes, work order submitted
 2. sign outside of restroom broken with sharp edges, work order submitted
3. Structural Damage
 - a. Day Care – Cover to crawlspace behind the building is missing, owner of day care notified
4. Playgrounds/School Grounds
 - a. City-owned portion of Playground – Muddy hole with standing water, city contacted
5. Overall Rating: FAIR
 - a. Note: Work orders submitted on above noted items, day care owner and city contacted regarding the two items involving them.