

Williams Visit Report

School: Mt. Diablo High School

Visit Date: September 17, 2010

Facility Notes:

1. Mech/HVAC
 - a. Broken condensation line outside P-8
 - b. Cyclone fabric damaged on most exterior HVAC'S throughout Dance Studio and Weight Room Bldg.
2. Interior Surfaces
 - a. Locker doors protrude into hallways in the Science Bldg and Art Bldg.
 - b. Stairwell treads damaged and loose causing a trip/fall hazard in Academic Bldg
3. Overall Cleanliness
 - a. Academic Bldg - Graffiti on outside walkway and overall dirty and dusty landings
 - b. Commercial Bldg – Graffiti on walls and overall dirty and dusty landings
4. Electrical
 - a. Lights out in English Bldg, Main Gym Hallway, and A-11
 - b. Loose light covers in Main Gym Hallway
 - c. Commercial Bldg – Light cover missing. Unsecured data junction box.
5. Restrooms
 - a. Girls RR, English Bldg – Burned toilet cover dispenser
6. Sinks/Fountains
 - a. S-4 – Sink faucet loose, sink drain clogged
 - b. S-3 – Middle sink drain clogged
 - c. Fountains damaged/inoperable IBO of Dance Studio
 - d. Shop Bldg – Drinking fountains low to no pressure
 - e. Girls Locker Room – Fountain inoperable

Williams Visit Report

7. Playground/School Grounds
 - a. Library Area – Missing tree in courtyard causing a tripping hazard, placed a cone at effected area while onsite. Permanent solution needed – no work order submitted by district.

8. Windows/Doors/Gates/Fences
 - a. Home Economics Boys Restroom – Door is jamming
 - b. Main Gym – Door closer assembly leaking oil onto door surface and floor.
 - c. Soccer Field – Old cyclone fence fabric has exposed knuckles and barbed wire on top of fencing
 - d. Football Field – Main Entry Gate needs to be repaired.

9. Overall Rating: GOOD
 - a. Work orders submitted for all items with exception of one.