

# Williams Visit Report

**School: Highlands Elementary**

**Visit Date: September 3, 2010**

## **Facility Notes:**

1. Interior Surfaces
  - a. Room 35 – Ceiling tile with water stain
2. Electrical
  - a. Room 8, 35 – Lights out
  - b. Cafeteria – Lights out in back of room, work order submitted
3. Restroom
  - a. Cafeteria – Strong odor from boys bathroom, water pressure low in sink, sink dirty
  - b. Boys Restroom across from Room 18 – Exposed pipe, chipped tiles
  - c. Girls Restroom across from Room 22 – Corner cracked from floor to ceiling, missing grout
4. Playground/School Grounds
  - a. Courtyard – Three areas where bricks are missing, tripping hazard
5. Overall Rating: FAIR