

# Williams Visit Report

**School: Cesar Chavez Elementary**

**Visit Date: September 9, 2010**

## **Facility Notes:**

1. Interior Surfaces
  - a. Room 2 – Bookcase needs to be secured, wall damage around window from a leak, graffiti on windows
  - b. Room 35 – Boxes stacked on top of cabinets, bookcase needs to be secured
  - c. Room 40 – Bookcase needs to be secured and not free standing
  - d. Room 53 – Rubber base needs repair, threshold loose
  - e. Portable 47 – Peeling paint on ramp, floor tiles need repair at door, blinds broken, bookcase needs to be secured
  - f. Hall by 1B – Ceiling tile leak
2. Electrical
  - a. Room 40 – Light fixture out
3. Restroom
  - a. Boys Restroom by 41 – Graffiti on the back of entrance door
4. Structural Damage
  - a. Near Room 43 and 44 1<sup>st</sup> & 2<sup>nd</sup> floors – Cracks and structural damage
  - b. Outside Room 5 – Wall to ceiling beam damage
5. Roofs
  - a. Portable 51 – Drainpipe missing outside
6. Overall Rating: FAIR