

# Williams Visit Report

**School: Highland Elementary**

**Visit Date: September 1, 2010**

## **Facility Notes:**

1. Interior Surfaces
  - a. Rooms 12 – Under sink old water damage noted
2. Electrical
  - a. Cafeteria – Unused electrical plugs need socket covers
  - b. Room 12 – Four light diffusers missing
3. Sinks/Fountains
  - a. Auditorium – Both hand sanitizers empty, need socket plugs in electrical outlets
4. Fire Safety
  - a. Room 15 – Fire exit sign missing glass
5. Hazardous Materials
  - b. Room 7 – Hazardous cleaning products stored under sink
  - c. Room 10 – Hazardous cleaning products stored under sink
  - d. Room 12 – Hazardous cleaning products stored under sink
  - e. Room 15 – Hazardous cleaning products stored under sink
6. Structural Damage
  - a. Outside Room 14 – Peeling paint and large exposed nail sticking out
  - b. Outside Room 22 – Metal flashing broken and sharp
7. Overall Rating: GOOD