

Williams Visit Report

School: Stege Elementary

Visit Date: September 27, 2010

Facility Notes:

1. Interior Surfaces
 - a. Room 19 – Broken floor tiles under TV
 - b. Room 22 – Overhead storage issues, ceiling tile falling out
 - c. Room 24 – Broken floor tiles at entrance, overhead storage issues due to stacked boxes
 - d. Computer Lab – Desk blocking air vent
2. Overall Cleanliness
 - a. Girls Restroom by room 9 – Vent needs cleaning
3. Electrical
 - a. Room 22 – Ceiling light fixture not working
 - b. Room 24 – Electrical outlet plate missing
 - c. Cafeteria – Lights out, thermostat cover needs repair
 - d. Computer Lab – Light cover broken, light cover falling down
4. Restrooms
 - a. Boys Restroom by Room 10 – Spray button on sink missing, toilet seats loose, vent needs cleaning
 - b. Room 9/10 Restroom – Broken toilet seats, door stop broken on both outside doors
5. Sinks/Fountains
 - a. Room 18 – Low water pressure to drinking fountain
 - b. Room 19 – Low water pressure to drinking fountain
 - c. Playground – Water pressure low to fountain outside of room 9
6. Playground/School Grounds
 - a. Playground – Chipping paint on benches near playground structure
7. Windows/Doors/Gates/Fences
 - a. Room 18 – Door closure broken
8. Overall Rating: FAIR