

Williams Visit Report

School: Tara Hills Elementary

Visit Date: September 27, 2010

Facility Notes:

1. Interior Surfaces
 - a. Multi-Purpose Room – Exit sign falling off wall, floor tiles broken, hole in wall by kitchen, rubber baseboard pulling away from wall by women's restroom
2. Overall Cleanliness
 - a. Overhead storage issues regarding boxes on cupboards in rooms K1, N3, N4, P4
3. Electrical
 - a. Multi-Purpose Room – Light bulbs missing from fixture near center stage
4. Sinks/Fountains
 - a. Playground –
 1. I-wing drinking fountain has no water
 2. two K-wing fountains need adjusting
 3. P-wing fountain needs adjusting, spraying on the ground; work orders submitted for above items
5. Hazardous Materials
 - a. Room 17 – Cleaning supplies stored under sink
6. Structural Damage
 - a. Outside Beams on all Buildings – Caps of beams needing repair, rotting wood noted on a lot of them
7. Windows/Doors/Gates/Fences
 - a. Multi-Purpose Room – Handles on doors under stage broken
8. Overall Rating: GOOD