

Williams Visit Report

School: Verde Elementary School

Visit Date: September 15, 2010

Facility Notes:

1. Overall Cleanliness
 - a. Graffiti noted in several areas of playground
 - b. Multi-Purpose Room – Outside wall needs power washing and painting
2. Electrical
 - a. Room D16 – Broken outlet cover
 - b. Room D18 – Missing outlet cover
 - c. Room A00 – Light switch cover broken
3. Restrooms
 - a. Boys Restroom B22 – Mirror missing
4. Sinks/Fountains
 - a. Sink loose or not working in rooms C12, D16, D18 and Library
 - b. Outside Room A00 – Drinking faucet leaks
 - c. Near B07 – Water pressure too high
5. Fire Safety
 - a. Computer lab – No fire extinguisher sign, extinguisher out of date, exit light not working
 - b. Kitchen – Missing fire extinguisher
6. Hazardous Materials
 - a. Cleaning supplies stored under sinks in several rooms
7. Structural Damage
 - a. Roof vent screens missing throughout campus
8. Playground/School Grounds
 - a. Hole in pavement in back of building, tripping hazard

Williams Visit Report

9. Windows/Doors/Gates/Fences
 - a. Room A00 - Bottom of door deteriorating
 - b. Multi-Purpose Room – Broken window, main gate too heavy to close, stage door does not close
 - c. Multiple classroom doors are rotting
 - d. Above B10 and B06 – Windows with multiple BB Gun holes

10. Overall Rating: FAIR