

# Williams Visit Report

**School: Wilson Elementary**

**Visit Date: September 1, 2010**

## **Facility Notes:**

1. Interior Surfaces
  - a. Earthquake proof bookshelves in rooms 24 and 23
  - b. Missing ceiling tiles in rooms 18, 14, and Library
  - d. Rm. 18 – Missing floor tiles and wires on floor need to be covered or removed
  - e. MPR – Broken door.
  
2. Electrical
  - a. Electrical outlet covers missing in rooms 21, 14, and 7
  - b. Rm. 14 – Speaker box needs cover – wires hanging out
  - c. K-1 – Power strip hanging in the air at student level and light duty extension cord near sink within student reach.
  - d. Library – Extension cord running cross the floor and light diffuser missing.
  
3. Restrooms
  - a. MPR, Girls Restroom - Broken mirror and sanitary dispenser is broken leaving sharp metal edges exposed to students
  - b. Boys Restroom near room 12 – Lacks ventilation, bad odor.
  - c. Girls Restroom near room 8 – Leaking toilet
  - d. Boys Restroom near room 8 – Stall does not lock, leaking urinal
  
4. Sinks/Fountains
  - a. Playground Fountain – Water shoots out of fountain onto floor
  
5. Fire Safety
  - a. Room 23 – Emergency window break released blocked by bookshelf
  - b. MPR – Exit light is out
  
6. Hazardous Materials
  - a. Hazardous Materials with in student reach in rooms 18, 14, and 9
  
7. Playground/School Grounds
  - a. Broken slide

# Williams Visit Report

8. Windows/Doors/Gates/Fences
  - a. Outside room 14 chain link fence is broken.
  - b. Broken window outside Boys Restroom near room 8
9. Overall Rating: - FAIR