

# Williams Visit Report

**School: El Cerrito High School**

**Visit Date: September 16, 2010**

## **Facility Notes:**

1. Interior Surfaces
  - a. Small Gym – Base trim missing
2. Electrical
  - a. Room B104 – Cords need bundling
  - b. Room B204 – Cords need bundling
3. Restrooms
  - a. B Wing 2<sup>nd</sup> Floor Boys – Missing faucet button
  - b. Gym Girls – Door will not close
  - c. Girls Locker Room – Showerhead missing
4. Sinks/Fountains
  - a. Room C301 – Front sink broken
5. Playground/School Grounds
  - a. Most fire extinguisher boxes have locks broken, potential vandalism problem
6. Windows/Doors/Gates/Fences
  - a. Room B303, C301 – Handle missing on cabinet
7. Overall Rating: GOOD