

Williams Visit Report

School: Juan Crespi Middle School

Visit Date: September 22, 2010

Facility Notes:

1. Interior Surfaces
 - a. Room 310 – Missing and loose base
 - b. Boys Locker Room – Lockers broken
 - c. Girls Locker Room – Lockers broken
 - d. Halls - Floor tiles need repair by Room 210
 - e. Stairs 100 Wing – West hall treads need repair

2. Overall Cleanliness
 - a. Room 206 – Storage room too full of items

3. Electrical
 - a. Lights out in rooms 100, 203, 206, 300, 301, 302, 305, 310
 - b. Light covers missing in rooms 202, 302, 308, 310
 - c. Room 204 – Need GFI outlets at sinks
 - d. Room 206 – Electrical panel blocked, access needed
 - e. Kitchen – Outlet cover missing in snack bar area
 - f. Café – Exit light out
 - g. Gym – Exit sign broken
 - h. Boys Locker Room – Lights out, emergency light on exit sign out
 - i. Girls Locker Room – Lights out
 - j. Halls – Wire hanging from alarm box and going into electrical panel by room 306

4. Restrooms
 - a. Boys Locker Restroom –Graffiti, light cover missing, faucet and toilet seat broken
 - b. Girls Locker Restroom – Broken soap dispenser, graffiti, missing light cover
 - c. Boys Restroom East – Ceramic tile broken, soap dispenser broken, faucet broken
 - d. Boys Restroom Quad Area – No soap dispenser, cracked toilet, screws sticking out of panel, left panel door missing with sharp hinges, graffiti, missing electrical box cover at ceiling
 - e. Girls Restroom Quad Area – Broken toilet seat
 - f. Boys Restroom West – Closed, used for storage

Williams Visit Report

- g. Girls Restroom West – Closed, used for storage
5. Sinks/Fountains
- a. Room 204 – Faucet not working
 - b. Hall fountain by room 209 – Broken faucet button, leaking and over spraying
6. Fire Safety
- a. Room 203 – No fire extinguisher
 - b. Kitchen – Fire extinguisher out of date
 - c. Halls - Fire extinguishers missing by Rooms 100, 105
7. Overall Rating: FAIR